LIQUID EFFLUENT

Central Facility Area (CFA) Sewage Treatment Plant (STP) Results for 2004

The WLAP for CFA STP (LA-000141-01) requires that the influent from the lift station (CFA-LS1) be sampled monthly and the effluent prior to the pivot (CFA-STF) be sample monthly during periods of operation for the following parameters:

| Influent (CFA-LS1) | Effluent (CFA-STF) |
|-------------------------------|-------------------------------|
| Daily flow | Daily flow |
| Total Kjeldahl nitrogen | Total Kjeldahl nitrogen |
| Nitrate + nitrite as nitrogen | Nitrate + nitrite as nitrogen |
| Biochemical oxygen demand | Biochemical oxygen demand |
| Chemical oxygen demand | Chemical oxygen demand |
| Total suspended solids | Total suspended solids |
| pH | pH |
| | Total phosphorus |
| | Fecal coliform |
| | Total coliform |

However, the permit does not specify any concentration limits for either the influent or the effluent, nor does it specify a permit year flow limit.

During the first quarter of 2004:

- The pivot was not operational; therefore, the effluent was not sampled.
- All permit-required parameters for the influent were within historical ranges.
- There were no permit noncompliances.

During the second quarter of 2004:

- The pivot was operational starting on June 28, 2004, and all influent and effluent permit-required parameters were within historical ranges.
- There were no permit noncompliances associated with the influent or effluent.

During the third quarter of 2004:

- The pivot was operational, and all influent and effluent permit-required parameters were within historical ranges.
- There were no permit noncompliances associated with the influent or effluent.

During the fourth quarter of 2004:

- The pivot was operational through October 21, 2004, and all influent and effluent permit-required parameters were within historical ranges.
- All permit-required samples were collected for both the influent and effluent; however, due to laboratory error, biochemical oxygen demand results were not obtained for the October sample, which resulted in a permit noncompliance; however, it did not endanger public health or the environment.

FOR MORE INFORMATION

Contact: Roger Wilhelmsen 208-526-9401 rnw@inel.gov

